

SECRET**PRIORITY**
OUT58591*multi*

1966 MAY 20 21 00Z

P 202045Z
FM NPIC WASHDC
TO RUCSC/SAC OFFUTT AFB OMAHA NEB
RUCVAA/4080 STRAT WG OL 19 BARKSDALE AFB LA
RUCVAA/2D RTS BARKSDALE AFB LA
RUEKDA/DIA WASHDC
RUECYH/NAVRECONTECHSUPPCEN SUITLAND MD
RUEPIA/CIA WASHDC
RUWBKN/15TH AF MARCH AFB RIVERSIDE CALIF
RUWGAA/2 AF BARKSDALE AFB LA
BT
S E C R E T CITE NPIC 7271.

15TH AF (FOR DI), SAC (FOR DIM/GOLDEN TREE/DOCR, DM 4) 2D AF (FOR DI).

1. CAMERA B-125 WAS USED IN MISSION 8094 FLOWN ON 18 MAY 1966. PROCESSING WAS ACCOMPLISHED BY BARKSDALE.

2. ORIGINAL NEGATIVE:

A. THE EXPOSURE WAS ADEQUATE AND THE RESOLUTION IS GOOD.

B. 9R SIDE: EDGE FOG IS PRESENT ALONG BOTH EDGES THROUGHOUT. SPOT STATIC OCCURS INTERMITTENTLY ALONG THE OUTBOARD EDGE THROUGH FRAME 1230. MINOR ROLLER CHATTER IS PRESENT ALONG THE INBOARD EDGE. A MANUFACTURING SPLICE IS LOCATED THROUGH FRAME 950.

C. 9L SIDE: ROLLER CHATTER OCCURS ALONG THE INBOARD EDGE. SPOT STATIC IS PRESENT ON THE OUTBOARD EDGE FOR APPROXIMATELY THE FIRST 1200 FRAMES. EDGE STATIC OCCURS ON THE OUTBOARD EDGE THROUGHOUT. INK TRANSFER FROM THE LEADER IS PRESENT ON FRAMES 0001 AND 0300. THE IR POSITION INDICATOR IS MISSING THROUGHOUT. A PATTERN OF MINUS DENSITY DOTS APPROXIMATELY 7/8" FROM THE OUTBOARD EDGE AND 1 3/4" APART WAS NOTED

23 MAY 1966

DISTRIBUTION		
Cy/fig.	Office	Action
1	File	
2	CO	
	ADMIN	
	SEC BR	
	P & DS	
	CSD	
	IPD	
	PD	
	PSD	
	PSD-ICB	
349	TID	✓
77	IAD	
	PAG	
	DIAXI-4	
	SPAD	
	NSA-LO	
	DIA-AP	

Advance copy
Sanitized

SECRET

-2-

INTERMITTENTLY ON ABOUT 1000 FRAMES BEGINNING AROUND FRAME 0709. A SERIES OF EMULSION ABRASIONS IS APPARENT ON FRAMES 0002 AND 2698. FOG WAS NOTED IN FRAME 1794. A MINUS DENSITY "COMET" IS PRESENT IN FRAME 1317. FOREIGN ADHESIVE SUBSTANCE WAS NOTED ON THE EMULSION OF FRAMES 2691, 2692, 2693, AND 2694. AN EMULSION LIFT ON FRAME 2694 IS DEPOSITED ON THE BASE OF THE SAME FRAME. FLECKS OF TITLING ADHERED TO THE EMULSION WAS NOTED ON THE ABOVE MENTIONED AND SURROUNDING FRAMES. FOREIGN SUBSTANCE IS ADHERED TO THE EMULSION ON FRAME 2699. A CRIMP TOWARD THE BASE IS PRESENT ALONG THE INBOARD EDGE FROM FRAME 2697 TO FRAME 2699. A MANUFACTURER'S SPLICE IS PRESENT IN FRAME 1062 WITH IT'S ASSOCIATED DEGRADATIONS APPARENT IN FRAME 1064.

D. BOTH SIDES: THE LAST TITLED FRAME IS 2731.

E. THERE WERE NO MAJOR PROCESSING OR CAMERA MALFUNCTIONS.

3. POSITIVE:

A. THE PI SUITABILITY IS GOOD.

B. THE PRINTING AND PROCESSING WERE GOOD.

C. CLOUDS DEGRADED OR OBSCURED 15 PERCENT OF THE

MISSION.

GP-1

S E C R E T

--END OF MESSAGE--